

Bruker Dimension Icon Atomic Force Microscopy – Air Scan




Bruker's Dimension icon Atomic Force Microscope (AFM) System allows for multiple experimental scanning modes that utilize Bruker's new ScanAsyst algorithm. Users can perform scans in air and fluid, using Tapping Mode or Contact Mode. Available experimental setups include, Magnetic Force Microscopy, Peak Fore Quantitative NanoMechanics, Force Imaging, and Surface Potential Imaging. The maximum step height measurement is approximately 10 µm, with a scan range of 100µm x 100µm. ScanAsyst Air tips and installation are currently provided by NCF, however, special tips needed for user specific experiments can be purchased by the user from Bruker. NCF can also purchase tips on the user's behalf at a fee.

Experiment Setup

- 1. Open the Nanscope software on the desktop. As the software starts up, the laser is automatically turn on.
- Once started, in the Select Experiment window, click on the type of experiment you would like to perform in the 1st section.
 - a. Typically, ScanAsyst, but others experimental categories are available
 - b. Click on ScanAyst in Air in the 2nd section.
 - c. Click on the selected experiment in the 3rd section.
 - d. Click on Load Experiment.




3. In the Workflow Toolbar window, click on Setup.



4. Click on button called **Move to the Alignment Station** in **section 2.1 of Align Laser on Probe**. The system will move the laser-detector assembly to the alignment station located on the stage.




Align the laser by centering it on the tip using the four knobs on the laser assembly (turn the knobs very slowly).
 For reference, click on the videos in sections 2.2 and 2.3 of Align Laser on Probe.



6. Click on the button called **Return from Alignment Station** in **section 3.1 of Focus Tip**. Wait for the laser-detector assembly to return from the alignment station.

3 Focus Tip	
3.1 Move back from Laser Alignment Station	
Return from the Alignment Station	
3.2 Use focus controls to focus optics on cantilever	
Focus Controls	
3.00 %	

- 7. In **section 3.2**, use the buttons called **Focus Controls** to focus the camera on the tip. You can change the speed at which this is done by using the speed control next to the Focus Controls.
- 8. Click on the tip position on the probe image to locate the cantilever. This centers the red cross-hairs on the cantilever. You can zoom in or out, and adjust the illumination using the controls at the bottom of the image.



- 9. Using the track-pad, move the laser-detector assembly up to make sure that it is higher than the sample. This ensures that the tip doesn't crash into the sample as you move in the sample.
 - a. Press and hold Lock
 - b. Scroll the ball up once to make the assembly move up.





10. In the **Workflow Toolbar**, click on the **Navigate**.

Workflow Toolbar	ĸ
Scan Asyst ScanAsyst in Air	-
Setup	
Navigate ← 1	. Click on "Navigate'
Check Parameters	
Engage	-
🤝 Scan	
Samp Ramp	-
🜲 Withdraw	

11. In section 1.1 of Load Sample, click on Sample Load Position.



12. Place your sample on the stage. Turn on the vacuum if necessary.



- 13. To make sure that your sample doesn't crash into the tip, check that the laser-detector assembly is above the surface of your sample. If it is, go to step 14. If not, move the laser-detector assembly up by doing the following
 - a. Press and hold Lock. Then press and hold Focus.
 - b. Scroll the ball up once to make the assembly move up.
- 14. Move the sample in by doing the following
 - a. Press and hold Lock
 - b. Scroll the ball once to move your sample underneath the tip.
- 15. In section 2.1 of Focus on Sample, click on Sample (default)

2	Focus Sample
	2.1 Select Focus Method
	Sample (default)
	2.2 Adjust focus by moving scan head up or down
	Scan Head
	Find Surface
	Be careful, adjusting focus position too fast may cause tip to contact surface

16. Reduce the illumination in the image. In section 2.2 of Focus on Sample, click on Find Surface. The scan-head (laser-detector-tip) assembly will approach the sample and stop once it has detected the surface.


Note: If your sample is not reflective or is transparent, the software will be unable to find the surface. You will have to find the surface manually. This is covered in the Appendix. If the software was unable to find the surface, skip to the Appendix and then return to step 20.

- 17. You can further lower the scan-head using the control on the side to get a clearer image of the sample surface.You can adjust the speed at which this is done. ALWAYS USE A LOW SPEED WHEN LOWERING THE SCAN-HEAD.
- Move to the region of interest on your sample by using the XY Controls in section 3.1 of Navigate to Scan Centerpoint. Alternatively, you can use the track ball to move as well.

3	Navigate to Scan Centerpoint
44	3.1 Navigate to a region of interest
	XY Control

Scan Setup

19. In the Workflow Toolbar, click on Check Parameters.




20. You may edit any of the following parameters. Do not edit parameters in Feedback or Limits.

B	Scan	
I	 Scan Size 	500 nm
I .	 Aspect Ratio 	1.00
L	 X Offset 	0.000 nm
	 Y Offset 	0.000 nm
	 Scan Angle 	0.00 °
L	 Scan Rate 	0.977 Hz
L	Samples/Line	512
B	Feedback	
	 Feedback Gain 	5.000
	 Peak Force Setpoint 	0.006375 V
	ScanAsyst Auto Control	On
B	Limits	
L	Z Range	13.2 µm
	 Reduced Z Delay 	2.00 s
	Z Auto Center Boundary	0 %


- a. Scan size choose a small scan size in the beginning, once you see everything is working fine, then choose a higher scan size. Maximum scan size is 100 μm.
- b. Aspect Ratio x-y image size
- c. **X Offset** shifts the tip in the x-axis (max distance is 45 μ m)
- d. **Y Offset** shifts the tip in the y-axis (max distance is 45 μ m)
- e. **Scan Rate** rate at which the scan is performed. The software can change this at any time if it detects any irregularities in the peak-force feedback.
- f. **Samples/Line** resolution of the scanned image. Higher Resolution means better image quality but longer scan time.

Scanning


- 21. Before scanning, double check your parameters, and the location of the sample and tip. If everything is okay, you may proceed to the next step. If not, revisit the steps 19 and 20 and perform them again.
- 22. In the Workflow Toolbar, click on Engage. A dialog box will pop-up as the process starts. It is important to be vigilant here. If your notice anything strange, click on Abort in the dialog box on the screen.
- 23. The screen will change to show the image below. will




24. Make sure the green bar at the bottom of the window remains green. If it turns yellow or red, immediately click Withdraw in the Workflow Toolbar, then repeat steps 21 – 25. Try reducing the scan size. If the green bar still changes to red or yellow after this, call the NCF office for assistance.



25. The toolbar below shows so of the actions you can perform while scanning.




26. You can capture the image using any of the options in the capture toolbar and you choose to save the image in a directory you wish.




27. To view the images in your directory, click **Directory** view button and select your directory again.



28. Once done scanning, click Withdraw on the Workflow Toolbar at least 3 times.



Click on Navigate in the Workflow Toolbar. Then click on Sample Load Position in section 1.1 of Load Sample.
 Unload your sample.



2. Click on: "Sample Load Position"

Load Sample
1.1 Move stage to same bad position, if desired
Semple Lood Position Sample Scan Position
Focus Sample
2.1 Select Focus Method
Sample (default) Tip Reflection 2.2 Adjust focus by moving scan head up or down
Find Surface
Be careful, adjusting focus position too fast may cause tip to contact surface
Navigate to Scan Centerpoint
3.1 Navigate to a region of interest

- 30. If you choose to scan another sample, you should check the deflection and sum voltages first since they may or may not have changed. Click on Setup in the Workflow Toolbar
 - a. If the deflection voltages have drifted to be > 0.5 V or the sum voltage had dropped below 4 V, repeat steps 3 – 28.
 - b. If not, click on Navigate in the Workflow Toolbar and repeat steps 10 28
- 31. If you are not scanning another sample, click the close button at the top of the software. This will shut off the laser and the rest of the system. Do not turn off the computer.


Appendix


Sample Focus When Find Surface Doesn't Work

Sometimes the Find Surface function can't find the surface of the sample to be scanned. This can happen if the sample if not reflective or is transparent. In cases like this, the objective will be to focus on the sample edge first.

Once you have completed steps 1 - 15,

Move to the edge of the sample by using the track-ball until you the edge of your sample is underneath the tip.
 If you look at your sample, you should be able to see a small light illuminating the edge of your sample.







2. Now slowly lower the scan-head using the control on the side to get a clearer image of the sample edge. You can adjust the speed at which this is done. ALWAYS USE A LOW SPEED WHEN LOWERING THE SCAN-HEAD.

2 Focus Sample	
2.1 Select Focus Method	d
J	
Sample	e (default) Tip Reflection
2.2 Adjust focus by mov	ing scan head up or down
Find Surface	Scan Head Speed 20.0 %
Be careful, adjusting for	cus position too fast may cause tip to contact surface

You can also lower the scan-head down by using the track-ball

- a. Press and hold Focus
- b. Scroll the ball until the sample edge is in focus.





3. Once you the sample edge is in focus, move to the sample surface by using the track-ball or by clicking the arrows in the XY Controls in section 3.1 of Navigate to Scan Centerpoint.

3	Navigate to Scan Centerpoint
+‡+	3.1 Navigate to a region of interest
	XY Control